
County of Riverside ASSESSOR MAP SECTION: 107


Subdivision of Tract Name	Mod Pobe	Lots	Recor	-	Subdivision	or 7	ract Name	Mdp Pode	Ŀ6ł k		orders
		Por. Blk.63 Blk. 61; 2, 4-5.	Book	S A				Pote		850K	Pdo
RIVERSIDE LAND & IRRIGATING Co.	05	Bik. 61; 2, 4-5.	1	70						+-	+-
<u>"</u>		Blk. 62; 1, 8-9	"	"							-
<i>H</i>	06	BIK. 62; 2-7,10	"	11							
**************************************	03	Blk. 62; 2 - 7, 10 Blk. 63; 12 - 13 Blk 63; par. 15 - 16	"	"						100	1
SOUTH RIVERSIDE LAND & WATER Co.		BIK. 33, 10	9	5.8. 6,8					25/24 - 22 - 23/25/25		
"	10	Blk 34: 9-11	ir.	"						100	
"		BIK 35; 5-6	,,	"							
		BIK. 36; por. 2	"	"							
,	1	BIK. 34; 1-8,BIK. 29;11=1	2"	"					1.71		L
"		BIK 28:9, II=12.BIK 35; 1-4	1985	"							
		BIK 29: 5, 7-10	"	".					la realizati		
"	1	Blk 33;7-9	"	"			<i>t</i> : =				
		BIK 33; 1-6. BIK 32; 1-3	"	"							
<i>"</i>		BIK 31; 1-6. BIK 30;4-12	"	"	PARCEL	MAF		05	1-2,A	17	9
					PARCEL.	MAP		18	Forcels 1-4	44	65
SUB. lot I, BLK. 32 SO. RIVERSIDE	17	1-10	9	S.B. 30	"	"	15953	18	" 1-4	77	10
700.1011, BEN.02 00.11112NOID2					"	4	13085	08	. " /-3	25	
CAJALCO TRACT No.I	07	por 183, 2, 4-6,8=11	8	38	"	ii	16003	11	" 1-4	88	79
"		por. [8 3	"	"	"	"	18038	03	1 1-4	113	76,
					"	"	18665	09	" 1=2,0	115	49
TRACT No. 2673	12	3-15, 24-80	49	45.4	, "	#	19096	//	" /-6	115	93
,		1-2, 16 - 23	"	"			Mar Darie				
" 5484	08		105	38,		To a					
Tract No. 17225		1-38	117	6-8							
Tract No. 10,168-1		1- 35	110	49- 51							
" " 15388	The second second	1-13		38- 39							
" " 11804	21	1-36		10/11	Record of Sur	VEV		02	POR PAR, 2051-68 PAR. 2051-6A	7/	77
" " 18464		1-164,C-K, 174-241	137	82-	11 "						
10404	22	7 70 7,0 11,11 2 21	1	69	" "				par. 1-2 par. 3-8	20	3
					RECORD of SURS	-			par. 9-11		3

10/8

BK. No. 107_

Subdivision of Tract Name	Mep Page	Leis	Recorde Beak	P938	Subdivision of Tract Name	Med Page	Lets	Received Resk Be	is bbe
1									
									÷.
1									-
				-					-
				_					-
		·				1			-1
				-		1			-
								28.00	
						-			-
						-			
						-			
						ļ			-
									_
		*							
		•							
		,,							
									-
				(Carlotter)					
						T			
									72 000
			1					-	7.00





MOUNTY OF RIVERSIDE OF THE SIDE OF THE SID

DEPARTMENT OF HEALTH

LOCAL SOLID WASTE MANAGEMENT ENFORCEMENT AGENCY

September 27, 1988

Mr. Norm Lostbom, Deputy Director Building & Safety - Land Use % Mr. Andy Nguyen 1777 Atlanta, Suite G-5 Riverside, CA 92507

RE: Tract 10168-1

The Local Solid Waste Management Enforcement Agency for Riverside County (LEA) requests that you require our clearance prior to your construction approval of Tract 10168-1.

Tract luiss-1 is located next to the closed Corona Landfill which raises our concern for landfill gas migration into the proposed development.

The property should be evaluated for purposes of requiring installation of a landfill gas migration control system. Permanent landfill gas monitoring wells should be in place and routinely monitored prior to construction approval.

Your assistance would help assure that the proposed residential home development would be protected from landfill gas migration.

If you have any questions regarding this letter, please call me at (714) 787-6543.

Sincerely,

Utra (dana igo Steven L. Samaniego, R.S. Supervising Sanitarian, I.EA

SI.S:r2

cc: John Fanning, Chairman, LEA Robert Nelson, Director, Riv. Co. Waste Mgmt. Dept. P.O. Box 1370 Riverside, California 92502, Phone (714) 787-6543

SOLID WASTE MANAGEMENT ENFORCEMENT AGENCY 中 COUNTY OF RIVERSIDE 39:40 Walt 55.5 45 W

518-04 DEPARTMENT OF HEALTH

September 27, 1988

Mr. Norm Lostbom, Deputy Director Building & Safety - Land Use & Mr. Andy Nguyen 1777 Atlanta, Suite G-5 Riverside, CA 92507

AND SON

RE: Tract 10168-1

our for Solid Waste Management Enforcement Agency County (LEA) requests that you require prior to your construction approval of T The Local Riverside clearance 10168-1.

Tract 10168-1 is located next to the closed Corona Landfill which raises our concern for landfill gas migration into the proposed development.

The property should be evaluated for purposes of requiring installation of a landfill gas migration control system. Permanent landfill gas monitoring wells should be in place and routinely monitored prior to construction approval.

t the proposed protected from that be p Your assistance would help assure residential home development would landfill gas migration.

If you have any questions regarding this letter, please call me at (714) 787-6543.

Sincerely,

Steven L. Samaniego, R.S. Supervising Sanitarian, LEA

- Gron

SIS: rz

Co. Waste Mgmt. Dept cc: John Fanning, Chairman, LEA Robert Nelson, Director, Riv. P.O. Box 1370 Riverside, California 92502, Phone (714) 787-6543